

香港粉嶺安居街33號

佳力高試驗中心有限公司 CASTCO TESTING CENTRE LIMITED

CASTCO TESTING CENTRE EI

33, On Kui Street, Fanling, Hong Kong. 29A, On Chuen Street, Fanling, Hong Kong. Website: www.castco.com.hk

Tel: 2597 8333 Fax: 2597 8399

> Testing Laboratory

香港粉嶺安全街29A號 25 E-mail: info@castco.com.hk W

Test Report

Testing of products for use in contact with drinking water

Date of issue: 13-04-2018

Page 1 of 2

Castco LRN: EN0180323-1

Details as supplied by customer

Name of Customer:

Purdon King (Internation) Limited

Address:

19/F., Tak Lee Commercial Building, 113-117 Wan Chai Road, Hong Kong

Job Title:

--

Sample details as supplied by customer

Date of Sample Received:

23-03-2018

Brand Name:

Pegler

Manufacturer:

Pegler Yorkshire / Model no.: PB100

Origin:

UK

Test Method(s):

1) AS/NZS 4020:2005 Appendix H - Extraction of Metals

Remarks:

- I. Test results only relate to the specimen tested and showed on Appendix A.
- II. In-the-product exposure.
- III. The sample/s mentioned in this report is/are submitted/supplied/manufactured by the Client. Castco therefore assumes no responsibility for the accuracy of information on the brand name, origin of manufacture, consignment or any information supplied.
- IV. The following scaling factors are adopted from voluntary GA* Scheme of Water Supplies Department.

Scaling Factor	
Nil	
0.05	
0.01	
0.05	
0.01 for DN=>100 0.05 for DN<100	
0.1	
0.01	

Checked by:

Au Kwok Kin

Senior Chemist

Approved Signatory:

Cheng Chi Fai

Senior Manager

Form No.: ENV ASNZS 4020(2005) T dd 23/06/2017



佳力高試驗中心有限公司 CASTCO TESTING CENTRE LIMITED

香港粉嶺安居街33號香港粉嶺安全街29A號 E-mail: info@castco.com.hk 33, On Kui Street, Fanling, Hong Kong. 29A, On Chuen Street, Fanling, Hong Kong. Website: www.castco.com.hk

Tel: 2597 8333 Fax: 2597 8399



Test Report

Testing of products for use in contact with drinking water

Date of issue: 13-04-2018

Page 2 of 2 Castco LRN: EN0180323-1

Castco Sample ID: EN0180323-1(1) & EN0180323-1(2)

Test period: 26-03-2018 to 27-03-2018

Sample Identification No.: --

Specimen No.: BC0180319-002-MISL

Extraction Temperature: 20°C

Item	Metal Elements	Test Water Blank	'1/2" Ball Valve' 1st Extraction (mg/L) Test results were corrected by scaling factor: 0.01		Reporting Limit	WHO Limit
		(μg/L)	sample 1	sample 2	(µg/L)	(μg/L)
1	Chromium	<1.0	<1.0	<1.0	1.0	50
2	Nickel	<1.0	<1.0	<1.0	1.0	70
3	Copper	<5.0	<5.0	<5.0	5.0	2000
8	Cadmium	<0.20	<0.20	<0.20	0.20	3
9	Antimony	<0.30	<0.30	<0.30	0.30	20
12	Lead	<1.0	<1.0	<1.0	1.0	10

End of Report

Form No.: ENV ASNZS 4020(2005) T dd 23/06/2017



CASTCO TESTING CENTRE LIMITED **CASTCO TESTING CENTRE LIMITED**

Appendix A

Date of issue: 13-04-2018 Page 1 of 1 pages

Castco LRN: EN0180323-1

Description of Sample: '1/2" Ball Valve'



Tel: 2597 8333

Fax: 2597 8399

E-mail: info@castco.com.hk Website: www.castco.com.hk